

Work Order ID 71947

Thursday, July 14, 2011 9:50:09 AM



Page 1

Item ID: D205-634-011

Accept



Setup Start



Revision ID:

Stop



Item Name: Skidtube

Start Date: 7/14/2011 Start Qty: 1.00



Cust Item ID:

Required Date: 7/29/2011 Req'd Qty: 1.00



Customer:

Reference:

Run Start



Approvals:

Process Plan:

Date: 11-07-14

Tooling:

Date:

QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr

Revision Nbr

IIN D205-634

Rev F

100

0.00



DC

Memo

0.00

Document Control

Photocopy bluefile & type labels per PPP D205-634-011
CHG 009-007

11 07 21
BG 11-7-20

110

Pick Kit

0.00



Packaging

Memo

0.00

Packaging

11 07 21

120

QC4- 100% Inspect kits for completeness

0.00



QC

Memo

0.00

Quality Control

11 07 21

B71377

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 71947

Thursday, July 14, 2011 9:50:09 AM



Page 2

Item ID: D205-634-011

Accept



Setup Start



Revision ID:

Stop



Item Name: Skidtube

Start Date: 7/14/2011 Start Qty: 1.00



Cust Item ID:

Required Date: 7/29/2011 Req'd Qty: 1.00



Customer:

Reference:

Run Start



Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____

Stop



QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

130

0.00



Packaging

Memo

0.00

Identify and pack for shipping as per PPP D205-634-011

Location: _____
PPP rev: _____

140

0.00



QC

Memo

0.00

QC21- Final Inspection - Work Order Release

Quality Control

ME
11-07-21

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Thursday, July 14, 2011 9:50:17 AM

Page 1

Work Order ID: 71947



Parent Item: D205-634-011



Parent Item Name: Skidtube

Start Date: 7/14/2011

Required Date: 7/29/2011

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP Rev:P 02.08.28 Removed QC5 from Step 5 KJ
 IPP Rev:Q 08-08-12 now @ chg 006 (DSI 9417) DD verf:EC
 IPP Rev R 09.01.28 now chg 007 DSI9417 revB EC verf:DD IPP Rev:S
 10.12.01 as per chg008 DD verf:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D205-634-041 		Manufactured	No			110	Each	4.0000	1	1			
Replacement Skidtube													
				<u>Location</u>				<u>Loc Qty</u>					
				FG073				4					
				66454				2					
				69988				1					
				70144				1					
K10003 		Manufactured	No			110	Each	0.0000	1	1			
Saddle, D205-634-011													



71377

[Handwritten signature]



70 627 *[Handwritten signature]*

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries